

Mean	166.36	Type in mean from table for parameter of interest
Std. Dev.	143.05	Type in standard deviation from table for parameter of interest
Value	0	Type in value (specification or other) for parameter of interest
z value	-1.1630	
% under	12.2424	Possibility of you getting sick if in at risk population
% over	87.7576	Possibility of you staying healthy if not in at risk population
PPM under	122424	Possibility of you getting sick if in at risk population
PPM over	877576	Possibility of you staying healthy if not in at risk population
PPB under	122423890	Possibility of you getting sick if in at risk population
PPB over	877576110.23	Possibility of you staying healthy if not in at risk population