

Mean	156.08	Type in mean from table for parameter of interest
Std. Dev.	137.42	Type in standard deviation from table for parameter of interest
Value	0	Type in value (specification or other) for parameter of interest
z value	-1.1358	
% under	12.8024	Possibility of you getting sick if in at risk population
% over	87.1976	Possibility of you staying healthy if not in at risk population
PPM under	128024	Possibility of you getting sick if in at risk population
PPM over	871976	Possibility of you staying healthy if not in at risk population
PPB under	128024056	Possibility of you getting sick if in at risk population
PPB over	871975944.17	Possibility of you staying healthy if not in at risk population