

Mean	136.17	Type in mean from table for parameter of interest
Std. Dev.	124.74	Type in standard deviation from table for parameter of interest
Value	0	Type in value (specification or other) for parameter of interest
z value	-1.0917	
% under	13.7490	Possibility of you getting sick if in at risk population
% over	86.2510	Possibility of you staying healthy if in at risk population
PPM under	137490	Possibility of you getting sick if in at risk population
PPM over	862510	Possibility of you staying healthy if in at risk population
PPB under	137489569	Possibility of you getting sick if in at risk population
PPB over	862510430.60	Possibility of you staying healthy if in at risk population