

Mean	135.11	Type in mean from table for parameter of interest
Std. Dev.	124.54	Type in standard deviation from table for parameter of interest
Value	-239	Type in value (specification or other) for parameter of interest
z value	-3.0039	
% under	0.1333	Possibility of you getting sick if in at risk population
% over	99.8667	Possibility of you staying healthy if in at risk population
PPM under	1333	Possibility of you getting sick if in at risk population
PPM over	998667	Possibility of you staying healthy if in at risk population
PPB under	1332732	Possibility of you getting sick if in at risk population
PPB over	998667267.98	Possibility of you staying healthy if in at risk population